
SAMPLE Fictional data and illustrated photos. Not a real ClarityCam record. The code does not scan.

Site Condition Report

Sample report with fictional data. Report CC-SAMPLE-0001

Property	Contractor	Signed by client
418 Birch Ln Sampleville, MN	Example Roofing Co. Job: full roof replacement	Jordan Sample Oct 12, 2026, 7:41 AM CDT

Driveway: before and after



BEFORE, marked: crack. Oct 12, 7:38 AM CDT. 45.0000, -95.0000, within 6 m. Facing N.
Time checked against network at capture.




AFTER. Oct 19, 4:22 PM CDT. 45.0000, -95.0000, within 5 m. Facing N.
Time checked against network at capture.

Roof: before and after



BEFORE. Oct 12, 7:33 AM CDT. Within 5 m. Facing E.
Time carried from network check 17 min earlier.



AFTER. Oct 19, 4:18 PM CDT. Within 6 m. Facing E.
Time checked against network at capture.

Proof on this record

- **Recorded.** Time and GPS checks shown under each photo.
- **Sealed.** Photos unchanged since capture, by SHA-256 and device signature.
- **Witnessed.** Independent timestamp: existed no later than Oct 12, 2026, 12:58 PM UTC.

What this does not show. It cannot prove what caused a condition, or rule out a staged scene or a photo of a photo. Scan the code to check the evidence package in a browser. Nothing is uploaded.